



August 19, 1998

Mr. Matthew Moran
State of Vermont
Department of Environmental Conservation
Waste Management Division
Sites Management Section
103 South Main Street/ West Building
Waterbury, VT 05671-0404

RE: Initial Subsurface Investigation at Tallman's Store, Belvidere, VT;

VTDEC Site #93-1424

Dear Mr. Corse:

Enclosed please find Griffin's Report on the Investigation of Subsurface Petroleum Contamination at Tallman's Store in Belvidere.

Please call if you have any questions regarding the findings of the investigation or our recommendations.

Sincerely,

Kevin McGraw Project Manager

cc: GI Project #39841203

Enc.

# REPORT ON THE INVESTIGATION OF SUBSURFACE PETROLEUM CONTAMINATION

at
TALLMAN'S STORE
ROUTE 109
BELVIDERE, VERMONT

**JULY 21, 1998** 

Prepared for:

Jack F. Corse Jack F. Corse, Inc. P.O. Box 300 Cambridge, VT 05444

Prepared by:



P.O. Box 943 Williston, Vermont 05495 (802) 865-4288

Griffin Project #: 39841203

#### I. INTRODUCTION

This report summarizes the investigation of subsurface petroleum contamination at Tallman's Store located on Route 109 in Belvidere, Vermont (see Site Location Map and Area Map, Appendix A). The following investigation has been conducted to define more clearly the degree and extent of petroleum contamination which was detected in the soils at this site during the removal of two gasoline underground storage tanks (USTs) on June 21, 1993. Included in the report are the findings from the drilling along with the results of subsequent groundwater sampling conducted at the property. This work has been completed for Mr. Jack Corse by Griffin International, Inc. (Griffin) in accordance with the Work Plan and Cost Estimate for Additional Work at Tallman's Store, dated March 23, 1998.

#### II. HISTORICAL BACKGROUND

On June 21, 1993, two gasoline USTs were removed from the subsurface at Tallman's Store. One of the tanks was a 1,000-gallon tank and the other was a 500-gallon tank. Upon removal, both tanks appeared to be in good condition. Soil contamination was evident around both tanks and appeared to be from product piping and also from spillage around the USTs. The limits of contamination could not be determined during the tank closure due to the proximity of Route 109 on the south sides of the tanks. All soils from the excavation were backfilled to avoid collapse of the roadway.

In response to the soil contamination detected during the removal of the USTs, the Vermont Department of Environmental Conservation (VTDEC) requested additional work in order to determine the severity of contamination present at the site. The following report presents the findings from Griffin's Site Investigation conducted in April and May, 1998.

#### III. SITE DESCRIPTION

Tallman's Store is located on the north side of Route 109 in the Cold Hollow Mountains of north-central Vermont. The North Branch of the Lamoille River is located just south of Route 109 and approximately 65 feet south of the former tank locations. Local terrain in the vicinity of the store and Route 109 is relatively level, however, on either side of the river, the land slopes up hillsides to the north and south of the river (see Site Location Map). Based on the proximity of the river, groundwater flow beneath the site was estimated to be to the southwest. The elevation of the site is approximately 258 meters above mean sea level.

The area surrounding the site consists of a mix of commercial and residential uses primarily. The area is served by private water supplies. Tallman's Store and several of the neighboring residences obtain their water from springs located several hundred feet

north of the site. The springs are located substantially upgradient from the site on the slopes of the Cold Hollow Mountains. The residence across the street from the store obtains water from a drilled well (SW1). SW1 is located approximately 75 feet southwest of the former USTs at Tallman's Store. According to state records, it appears that this well is a drilled bedrock well and is 222 feet deep. This well reportedly has 56 feet of casing, has a yield of 1.5 gallons per minute, and was observed to be artesian. Three other residences located west of the store also obtain their water from private drilled wells (see Area Map in Appendix A).

2 ben non

The Surficial Geologic Map of Vermont maps the surrounding area as glaciofluvial kame gravel. Actual subsurface materials consist of fine sand, silt, and gravel in varying proportions.

depth to bedrock.

#### IV. SUBSURFACE INVESTIGATION

On April 29, 1998, four monitoring wells were installed by Adams Engineering using a truck-mounted vibratory drill rig. The monitoring wells, designated MW-1 through MW-4, were installed to help define the degree and extent of petroleum contamination in the vicinity of the former gasoline USTs. MW-1 was installed near the east end of the former gasoline tank pit. The boring for MW-2 was drilled on the west side of the former tank pit. MW-3 and MW-4 were installed in the estimated downgradient directions from the former tank pit area. The locations of the wells are shown on the Site Map in Appendix A.

Continuous core samples were obtained in each boring. Soil samples were screened for VOCs using a Photovac Model No. 2020 photoionization device. In addition, soil characteristics were recorded in detailed boring logs by the supervising Griffin hydrogeologist.

In the boring for MW-1, fine sand and silt were predominant from 3.5 to 9.5 feet below grade. Groundwater was encountered at approximately five feet below grade. Petroleum odors were observed in the soils from this boring. A maximum PID reading of 1,290 ppm was recorded for the soil sample collected at a depth of 3.5 to 4.5 feet below grade.

Soils retrieved from the boring for MW-2 were fine sand and silt from 1.5 to 6.5 feet below grade. From 6.5 to 8.5 feet below grade, fine and medium sand with some gravel was observed. Groundwater was again encountered at approximately five feet below grade. Petroleum odors were observed in all of the soil samples collected from this boring. A maximum PID reading of 1,550 ppm was recorded in soil collected from 1.5 to 4.5 feet below grade.

In the boring for MW-3, fine sand with some silt was observed from 3.2 to 6.8 feet below grade. Fine sand and gravel was encountered between 6.8 and 7.8 feet below grade. Groundwater was encountered at approximately 3.2 feet below grade. Petroleum odors

were observed in the soils from this boring. A maximum PID reading of 1,300 ppm was recorded for the soil sample collected at a depth of 4.5 to 5.8 feet below grade.

Soils retrieved from the boring for MW-4 consisted of fine sand and silt from grade to approximately 9.5 feet below grade. Fine sand and gravel was observed from 9.5 to 13 feet below grade. Groundwater was encountered at approximately 4.5 feet below grade. Petroleum odors were observed in the soils from this boring. A maximum PID reading of 1,510 ppm was recorded for the soil sample collected at a depth of 9.5 to 13 feet below grade.

The screens in monitoring wells MW-1, MW-2, MW-3, and MW-4 were set from 2.0' to 9.5', 3.5' to 8.5', 2.8' to 7.8', and 3.0' to 13.0', respectively. The monitoring wells were constructed with 1.5-inch diameter, Schedule 40 PVC riser and 0.010" slotted screen. A silica sand pack was placed around the screened portion of each well and a bentonite seal was placed in the annulus immediately above the sand pack. To complete the construction of each well, a road box was set in concrete at grade level. In addition, a locking well cap was placed on each monitoring well. The boring logs and well construction details for these wells are included in Appendix B.

#### V. WATER LEVELS AND WATER QUALITY

#### A. Water Table Elevations

Water table elevation measurements were collected from MW-1 through MW-4 on May 6, 1998. The water table was observed to be approximately 5 to 7 feet below grade at that time. The monitoring wells were surveyed in azimuth and elevation relative to the top-of-casing of MW-1 which has been assigned an arbitrary elevation of 100.00 feet. Liquid level monitoring data are presented in Appendix C.

Water table elevations have been plotted and contoured to illustrate the calculated gradient and direction of groundwater flow beneath the site (see Groundwater Contour Map, Appendix A). According to these data, groundwater is flowing to the southwest at a hydraulic gradient of 0.039.

#### B. Water Quality

Griffin collected groundwater samples at the site from all four monitoring wells. The groundwater samples were analyzed for petroleum compounds by EPA Method 602. The analytical results have been plotted to show the distribution of dissolved contamination across the site (see Contaminant Distribution Map, Appendix A).

Low to moderately high levels of benzene, toluene, ethylbenzene and xylenes (BTEX) were detected in the four groundwater samples. MTBE, a gasoline additive, was not detected in any of the samples. The Vermont Groundwater Enforcement Standards

(VGES) for benzene, toluene, and ethylbenzene were exceeded in the samples from MW-1, MW-2, and MW-4. The VGES for benzene was also exceeded in the MW-3 sample. A groundwater quality summary for this sampling event is presented in Appendix D. The Endyne laboratory report is also included in this appendix.

The trip blank and duplicate sample analytical results indicate that proper quality assurance and quality control were maintained during the sampling and analysis.

Water samples were also collected from two supply wells in the area. The residence directly across Route 109 from Tallman's Store utilizes a drilled artesian well (see SW1 on Area Map). Several other residences located directly west of the store also utilize drilled supply wells. Only one of these three (identified as SW2 on Area Map) could be sampled on the day of sampling since two of the homeowners were not present at the time. Water samples were collected from SW1 and SW2 on May 6, 1998. Petroleum compounds were not detected in either sample.

#### VI. RIVERBANK SOIL SAMPLING

On April 29, 1998, the bank of the North Branch of the Lamoille River was screened for signs of petroleum contamination. Soil samples were placed into plastic baggies and screened for VOCs using a PID. Stained soils were observed on the soils of the riverbank located south of the southwest corner of the Marshall residence (across Route 109 from Tallman's Store). A PID reading of 102 ppm was recorded for soil sample S5. VOCs were detected in three other soil samples at less than 10 ppm. A Riverbank Soil Sampling Location Map, included in Appendix A, presents the findings from the soil screening.

Sample S5 was submitted to Endyne Inc. laboratory to be analyzed for petroleum compounds by EPA Method 8020 and Total Petroleum Hydrocarbons (TPH) by Modified EPA Method 8015. BTEX were detected in the riverbank soil sample at a total concentration of 211.1 parts per billion (ppb). TPH were measured to be 151 ppm.

#### VII. RECEPTOR RISK ASSESSMENT

A receptor risk assessment was conducted to identify known and potential receptors of the petroleum contamination detected at Tallman's Store. A visual survey was conducted at the time of monitoring well installation and during the UST closure inspection. A determination of the potential risk to identified receptors was conducted based on proximity, groundwater flow direction and gradient, and contaminant concentration levels.

#### Water Supplies

As outlined in Section III of this report, the area in the vicinity of Tallman's Store is served by private water supplies. Tallman's Store and several of the neighboring residences obtain their water from springs which appear to be located upgradient of the site. The residence across the street from the store obtains water from a drilled well located approximately 75 feet southwest of the former USTs at Tallman's Store. Three other residences located west of the store also obtain their water from private drilled wells.

Given its location relative to the dissolved contaminant plume, the Marshall supply well (SW1) is potentially at risk. The supply well sample results indicated that it was not contaminated at that time. In addition, this well was observed to be an artesian well with water overflowing at the ground surface.

The other three private wells identified to the west of Tallman's Store (including SW2) do not appear to be located directly downgradient of the contaminant plume and are likely at minimal risk of impact.

#### Buildings in the Vicinity

Tallman's Store has a basement for the potential accumulation of petroleum vapors. This basement is located approximately 15 to 20 feet north of the former tank area. On April 29, the basement was screened for VOCs using a PID. Elevated levels of VOCs were not detected along the south wall of the basement, closest to the former UST area, and as such, it does not appear that the basement is being impacted by the petroleum contamination from the former USTs. In addition, the estimated groundwater flow direction is to the southwest, away from the Tallman's Store, suggesting that vapor impact from the subsurface contamination is not likely.

The basement of the Marshall residence, located across Route 109 from Tallman's Store, was also screened for VOCs on April 29. No elevated levels of VOCs were detected in the basement on that day. However, this basement is located downgradient of the source area and appears to be at risk of petroleum impact since the contaminant plume has reached this area.

#### Surface Water

The North Branch of the Lamoille River is located approximately 65 feet south of the former UST locations on the Tallman's Store property . This river appears to have been impacted to some degree as evidenced by the riverbank sample which contained BTEX contamination and exhibited staining.

#### VIII. CONCLUSIONS

Based on the investigation at this site, Griffin has reached the following conclusions:

- 1. In each of the four soil borings, silt and fine sand were predominant. Adsorbed petroleum contamination was detected in all four soil borings advanced for this site investigation.
- 2. The water table elevation beneath the site, as measured using the interface probe, ranged from approximately 5 to 7 feet below grade. Based on the water table elevation data collected in May 1998, groundwater beneath the site is flowing to the southwest at a hydraulic gradient of 0.039.
- 3. Low to moderately high levels of dissolved BTEX contamination were detected in the groundwater samples collected from the four monitoring wells. The Vermont Groundwater Enforcement Standards for benzene, toluene, and ethylbenzene were exceeded in most of these samples. MTBE, a gasoline compound, was not detected in any of the samples at the site.
- 4. Soil samples collected from the bank of the North Branch of the Lamoille River were observed to be impacted with petroleum contamination. Stained soils were observed directly south of the southwest corner of the Marshall residence (S5). This soil sample had a PID reading of 102 ppm, and the laboratory sample submitted from this location confirmed the presence of BTEX and MTBE. These results suggest that petroleum contamination from Tallman's Store has reached the river.
- 5. Water samples were collected from the two private drinking water supplies closest to the site. Dissolved petroleum contamination was not detected in either sample. The Marshall residence well is installed through the dissolved contaminant plume. This well is reported to be a true artesian well and, as such, may be at less risk of impact due to the upward hydraulic gradient of the bedrock aquifer.
- 6. The risk assessment for this site has determined that there is a risk to the Marshall residence supply well and basement. In addition, the North Branch of the Lamoille River has been impacted.

#### IX. RECOMMENDATIONS

Based on the above conclusions, Griffin recommends that a semi-annual groundwater monitoring schedule be initiated. During these site visits, liquid level measurements should be collected from all four groundwater monitoring wells prior to sampling. Groundwater samples should be analyzed by EPA Method 602. In addition, the basement of the Marshall residence should be screened for VOCs again during the next site visit and their water supply should be resampled during each semi-annual site visit. The first semi-annual site visit should be conducted in October of 1998.

Comments

Sample all wells by 8021b + 54-1.

Sample all wells by 8021b + 54-1.

Comments

There are all wells by the cittle of their from surple

There in to bedrock from sw 1095.


Team to bedrock from sw 1095.

## **APPENDICES**

## APPENDIX A

# Maps

Site Location Map
Area Map
Site Map
Groundwater Contour Map
Contaminant Distribution Map
River Bank Soil Sampling Location Map



JOB #: 39841203 SOURCE: USGS- JOHNSON, VERMONT AND COLD HOLLOW MOUNTAINS QUADRANGLES.




## TALLMAN'S STORE


BELVIDERE, VERMONT


SITE LOCATION MAP


DATE: 5/19/98 DWG.#:1


SCALE: 1:24000 DRN.:SB APP.:LR











# APPENDIX B

Well Logs

PROJECT TALLMAN'S STORE

LOCATION BELVIDERE, VERMONT

DATE DRILLED 4/29/98 TOTAL DEPTH OF HOLE 9.5'

DIAMETER 2.75"

SCREEN DIA. 1.5" LENGTH 7.5' SLOT SIZE 0.010"


CASING DIA. 1.5" LENGTH 1.7' TYPE sch 40 pvc

DRILLING CO. ADAMS ENGR DRILLING METHOD VIBRATORY

DRILLER GERRY ADAMS LOG BY L REED

GRI

DEPTH WELL NOTES BLOWS PER DESCRI



r 61 11117	ER <u>GERRY AD</u>	HOG DI	L REED	GRIFFIN INTERNATIONAL	<i>I, IN</i>
DEPTH IN FEET	WELL CONSTRUCTION	NOTES	BLOWS PER 6" OF SPOON & PID READINGS	DESCRIPTION/SOIL CLASSIFICATION (COLOR, TEXTURE, STRUCTURES)	DEPTH IN FEET
- 0 - 1 - 2 - 3 10 11 12 15 16 17 18 17 20 21 22 23 24 25 - 25 - 25		ROAD BOX LOCKING WELL CAP CONCRETE BENTONITE WELL RISER SAND PACK WELL SCREEN BOTTOM CAP UNDISTURBED NATIVE SOIL	0'-3.5' 1.0 ppm 3.5'-4.5' 1,290 ppm 4.5'-9.5' 700 ppm	Medium brown, fine SAND and coarse GRAVEL, (fill), dry.  Black stained, fine SAND and SILT, with few medium sand, trace coarse sand, damp, petroleum odor.  5.0' WATER TABLE  Brown, fine SAND, some silt, trace medium sand with 0.2' interbed of black stained medium sand, wet.  BASE OF WELL AT 9.5' END OF EXPLORATION AT 9.5'	- 0 1 2 13 15 16 17 18 17 18 19 22 23 24 25 25 25

PROJECT TALLMAN'S STORE LOCATION BELVIDERE, VERMONT

DATE DRILLED\_4/29/98\_TOTAL DEPTH OF HOLE \_8.5'


DIAMETER 2.75"

SCREEN DIA. 1.5" LENGTH 5.0' SLOT SIZE 0.010"


CASING DIA. 1.5"LENGTH 3.0' TYPE sch 40 pvc


DRILLING CO. ADAMS ENGR. DRILLING METHOD VIBRATORY

DDILLED GERRY YDAMS




DRILLER GERRY A	DAMS_LOG BY_	L REED	GRIFFIN INTERNATIONAL	. INC
DEPTH WELL IN CONSTRUCTIO	NOTES	BLOWS PER 6" OF SPOON & PID READINGS	DESCRIPTION/SOIL CLASSIFICATION (COLOR, TEXTURE, STRUCTURES)	
- 0 - 1 - 2 - 3 - 4 - 5 - 6 - 7 - 8 - 9 - 10 - 11 - 12 - 13 - 14 - 15 - 16 - 17 - 18 - 19 - 20 - 21 - 22 - 23 - 24 - 25 - 21	ROAD BOX LOCKING WELL CAP CONCRETE BENTONITE WELL RISER SAND PACK WELL SCREEN BOTTOM CAP UNDISTURBED NATIVE SOIL	0'-1.5' 1,400 ppm  1.5'-4.5' 1,550 ppm  4.5'-6.5' 1,360 ppm  8.5'-8.5' 700 ppm		- 0 -   - 2 -   - 3 -   - 13 -   - 15 -   - 16 -   - 17 -   - 18 -   - 17 -   - 20 -   - 21 -   - 22 -   - 24 -   - 25 -





DEPTH   NOTES   BLOWS PER 6" OF SPOON & PID READINGS   DESCRIPTION/SOIL CLASSIFICATION   NOTES   DESCRIPTION/SOI	)RILLI	ER <u>GERRY ADA</u>	AMS LOG BY_	L REED	GRIFFIN INTERNATIONAL	, INC
LOCKING WELL CAP CONCRETE   1	IN	CONSTRUCTION	NOTES	6" OF SPOON	INCOCINI MOM DOM OPHIBOR FORMAN	I IN I
<del></del>	- 1 - 2 - 3 - 4 6 10 11 12 15 16 17 18 19 21 - 22 - 23 - 24 - 24 - 24 - 24 - 24 - 24	-	LOCKING WELL CAP CONCRETE BENTONITE WELL RISER SAND PACK WELL SCREEN BOTTOM CAP UNDISTURBED	1.1 ppm  3.2'-4.5' 48 ppm  4.5'-5.8' 1,300 ppm  5.8'-6.8' 1,180 ppm  6.8'-7.8'	GRAVEL, dry.  3.2' WATER TABLE  Brown, fine & medium SAND, some silt, wet, slight petroleum odor.  Brown, fine SAND and SILT, wet, petroleum odor.  Black stained, fine SAND, petroleum odor.  Brown, medium SAND, fine sub-angular gravel, wet.  BASE OF WELL AT 7.8'	- 1 2 3 4 10 11 13 14 15 16 17 18 19 20 21 22 24 24 24 24



## APPENDIX C

**Liquid Level Monitoring Data** 

# Liquid Level Monitoring Data Tallman's Store, Belvidere, VT

5/6/98

Well I.D.	Top of Casing Elevation	Depth To Product	Depth To Water	Product Thickness	Specific Gravity Of Product	Water Equivalent	Corrected Depth To Water	Corrected Water Table Elevation
MW-1	100.00		5.05					94.95
MW-2	99.06		4.62					94.44
MW-3	98.85		5.26					93.59
MW-4	98.25		6.82					91.43

All Values Reported in Feet

Top-of-Casing Elevations Measured in Feet Relative to MW-1 set at 100.00'

# APPENDIX D

**Groundwater Quality Summary** 

**Laboratory Reports** 

# Groundwater Quality Summary Tallman's Store Belvidere, Vermont

May 6, 1998

				iriuy o,									
		Sample Point											
					Duplicate	Тгір							
PARAMETER	MW-1	MW-2	MW-3	MW-4	of MW-2	Blank	SW1	SW2	VGES				
Benzene	600.	2,460.	139.	2,290.	2,430.	ND	ND	ND	5.				
Chlorobenzene	ND	ND	ND	ND	ND	ND	ND	ND	100.				
1,2-DCB	ND	ND	ND	ND	ND	ND	ND	ND	600.				
1,3-DCB	ND	ND	ND	ND	ND	ND	ND	ND	600.				
1,4-DCB	ND	ND	ND	ND	ND	ND	ND	ND	. 75.				
Ethylbenzene	1,100.	1,420.	389.	1,620.	1,340.	ND	ND	ND	700.				
Toluene	2,720.	9,850.	386.	3,340.	9,680.	ND	ND	ND	1,000.				
Xylenes	3,840.	9,820.	568.	4,760.	9,310.	ND	ND	ND	10,000.				
Total BTEX	8,260.	23,550.	1,482.	12,010.	22,760.	ND	ND	ND					
MTBE	ND	ND	ND	ND	ND	ND	ND	ND	40				
BTEX+MTBE	8,260.	23,550.	1,482.	12,010.	22,760.	. ND	ND	ND					

All Values Reported in ug/L (ppb)

VGES - Vermont Groundwater Enforcement Standard

ND - None Detected

TBQ - Trace Below Quantitation Limit



32 James Brown Drive Williston, Vermont 05495 (802) 879-4333 FAX 879-7103

## REPORT OF LABORATORY ANALYSIS

CLIENT: Griffin International

PROJECT NAME: Tallmans Store

REPORT DATE: May 11, 1998 DATE SAMPLED: May 6, 1998 PROJECT CODE: GITS1544

REF.#: 120,219 - 120,226

Enclosed please find the results of the analyses performed for the samples referenced on the attached chain of custody. Chain of custody indicated sample preservation with HCl.

All samples were prepared and analyzed by requirements outlined in the referenced method and within the specified holding times. All instrumentation was calibrated with the appropriate frequency and verified by the requirements outlined in the referenced method. Blank contamination was not observed at levels affecting the analytical results.

Analytical method precision and accuracy was monitored by laboratory control standards which included matrix spike, duplicate and quality control analyses. These standards were determined to be within established laboratory method acceptance limits.

Individual sample performance was monitored by the addition of surrogate analytes to each sample. All surrogate recovery data was determined to be within laboratory QA/QC guidelines unless otherwise noted.

Reviewed by,

Harry B. Locker, Ph.D. Laboratory Director

enclosures



32 James Brown Drive Williston, Vermont 05495 (802) 879-4333 FAX 879-7103

#### **EPA METHOD 602--PURGEABLE AROMATICS**

CLIENT: Griffin International

PROJECT NAME: Tallmans Store

CLIENT PROJ. #: 39841203

DATE RECEIVED: May 7, 1998

REPORT DATE: May 11, 1998

PROJECT CODE: GITS1544

<del></del>			TROSECT COD	D. 01101344	
					-
Ref. #:	120,219	120,220	120,221	120,222	120,223
Site:	MW 1	MW 2	MW 2 Duplicate	MW 3	MW 4
Date Sampled:	5/6/98	5/6/98	5/6/98	5/6/98	5/6/98
Time Sampled:	9:46	10:03	10:03	9:39	10:10
Sampler:	W. Doe	W. Doe	W. Doe	W. Doe	W. Doe
Date Analyzed:	5/8/98	5/8/98	5/8/98	5/7/98	5/7/98
UIP Count:	>10	>10\	>10	>10	>10
Dil. Factor (%):	2.	1	1 1	2	1
Surr % Rec. (%):	94	96	92	81	80
Parameter	Conc. (ug/L)	Conc. (ug/L)	Conc. (ug/L)	Conc. (ug/L)	Conc. (ug/L)
Benzene	600.	2,460.	2,430.	139.	2,290.
Chlorobenzene	<50	<100	<100	<50	<100
1,2-Dichlorobenzene	<50·	<100	<100	<50	<100
1,3-Dichlorobenzene	<50	<100	<100	<50	<100
1,4-Dichlorobenzene	<50	<100	<100	<50	<100
Ethylbenzene	1,100.	1,420.	1,340.	389.	1,620.
Toluene	2,720.	9,850.	9,680.	386.	3,340.
Xylenes	3,840.	9,820.	9,310.	568.	4,760.
MTBE	<500	<1000	<1000	<500	<1000
			· · · · · · · · · · · · · · · · · · ·		·
Ref. #:	120,224	120,225	120,226		
Site:	SW1	SW2	Trip Blank		
Date Sampled:	5/6/98	5/6/98	5/6/98		
Time Sampled:	10:28	10:35	7:31		
Sampler:	W. Doe	W. Doe	W. Doe		
Date Analyzed:	5/7/98	5/8/98	5/7/98		
UIP Count:	Ó	0	0		
Dil. Factor (%):	100	100	100		
Surr % Rec. (%):	98	98	93		
Parameter	Conc. (ug/L)	Conc. (ug/L.)	Conc. (ug/L)		
Benzene	<1	<1	<1		
Chlorobenzene	<1	<1	<1		
1,2-Dichlorobenzene	<1	<1	<1		
1,3-Dichlorobenzene	<1	<1	. <1		
1,4-Dichlorobenzene	<b>  &lt;1</b>	<1	<1		
Ethylbenzene	<1	<1	<1		
<b>Foluene</b>	<1	<1	<1		
Xylenes	<1	<1	<1		
MTBE	<10	<10	<10		

Note: UIP = Unidentified Peaks TBQ = Trace Below Quantitation NI = Not Indicated

LNDYNE. INC.

Project Name: 3984/203

32 James Brown Drive Williston, Vermont 05495 (802) 879-4333

#### CHAIN-OF-CUSTODY RECORD

26737

Reporting Address: GRIFFIN INT'C Billing Address: CRIFFIN Site Location: TAUMAN STORE, BELINDERE, VT Endyne Project Number: Company: GKIACIN INTIL GITSISYY Sampler Name: WILLS Do = Contact Name/Phone #: 865 4298/ LAVRIE PEED Phone #: 865 4288 Lab# Sample Containers Sample Location Matrix Date/Time Analysis Sample Field Results/Remarks 5-6-98 Rush Required No. Type/Size Preservation BY 5" || mwi GW 0944 WOA/40ml HCI 602 120,220 nw2 1003 GW MW 2 DUPLICATE 190,991 GW 120,222 MW3 GW/ 120.225 MW 4 1010 GW 120.224 SW TAP/DW 1028 120,225 SW2 TAP DW 1035 120,236 TRIP BLANK 0731 160 4 Relinquished by: Signature Wills Que Received by: Signature Date/Time 5-6-98/1545 Relinquished by: Signature Received by: Signature Date/Time New York State Project: Yes Requested Analyses ρH TKN Total Solids Metals (Specify) 21 EPA 624 2 Chloride EPA 8270 B/N or Acid 7 Total P 12 TSS 17 Coliform (Specify) 22 EPA 625 B/N or A Ammonia N 27 8 EPA 8010/8020 Total Diss. P. 13 TDS 18 COD 23 EPA 418.1 4 Nitrite N EPA 8080 Pest/PCB 9 BOD, Turbidity 19 BTEX 24 EPA 608 Pest/PCB 5 Nitrate N Alkalinity Conductivity 20 EPA 601/602 25 EPA 8240 29 TCLP (Specify: volatiles, semi-volatiles, metals, pesticides, herbicides) 30 Other (Specify):

TCLP (Specify: volatiles, semi-volatiles, metals, pesticides, herbicides)

29 30

Other (Specify):

32 James Brown Drive CHAIN-OF-CUSTODY RECORD 26737 Williston, Vermont 05498 (802) 879-4333 Billing Address: LAIFFIN Project Name: 3984/203 Reporting Address: @RIFFIN INT'L Site Location: TRUMANA SIONE, BELINDERS, VT Sampler Name: WILLY DOE Company: GKIFFIN INTIL Endyne Project Number: Phone #: 865 42 66 Contact Name/Phone #: 865 4796/140#16 PEED Sample Analysis Sample Containers Field Results/Remarks Date/Time Preservation Sample Location ... Matrix Required Lab# 55-6-19 No. Type/Size HCI 602 waldel GW mwi MW2 MW 2 DUPLICATE GW W MW3 1. 精清 SW! TAPI DU 7 - CX vi. TAPLEN TRIP BLANK 多点 THE WAR THE THE - Sec. 1 13. **%** 3 Date/Time 5-6-98 1545 Relinquished by: Signature Wille Dec Received by: Signature Date/Time 11:00 Relinquished by: Signature Received by: Signature Requested Analyses No New York State Project: Yes EPA 8270 B/N or Acid EPA 624 Total Solids ...16 Metals (Specify) 21 26 TKN EPA 8010/8020 Coliform (Specify) 22 EPA 625 B/N or A 12 TSS . 1. 1985 S. A. Total P Chloride EPA 8080 Pest/PCB TDS 4.185 COD 🐁 23 EPA 418.1 8 Total Diss. P 13 Ammonia N Turbidity BTEX 24 EPA 608 Pest/PCB 19 BOD. Nitrite N 9. 25 EPA 8240 Conductivity 4 EPA 601/602 Nitrate N 10 Alkalinity 5



32 James Brown Drive Williston, Vermont 05495 (802) 879-4333 FAX 879-7103

#### REPORT OF LABORATORY ANALYSIS

CLIENT: Griffin International

PROJECT NAME: Tallman's Store DATE REPORTED: May 7, 1998 DATE SAMPLED: April 29, 1998 PROJECT CODE: GITS1452

REF. #: 119,914

Enclosed please find the results of the analyses performed for the samples referenced on the attached chain of custody record.

Chain of custody did not indicate sample preservation.

All samples were prepared and analyzed by requirements outlined in the referenced methods and within the specified holding times.

All instrumentation was calibrated with the appropriate frequency and verified by the requirements outlined in the referenced methods.

Blank contamination was not observed at levels affecting the analytical results.

Analytical method precision and accuracy were monitored by laboratory control standards which included matrix spike, duplicate and quality control analyses. These standards were determined to be within established laboratory method acceptance limits.

Individual sample performance was monitored by the addition of surrogate analytes to each sample. All surrogate data was determined to be within Laboratory QA/QC guidelines unless otherwise noted.

Reviewed by,

Harry B. Locker, Ph.D. Laboratory Director

enclosures



32 James Brown Drive Williston, Vermont 05495 (802) 879-4333 FAX 879-7103

#### LABORATORY REPORT

#### EPA METHOD 8020 COMPOUNDS BY EPA METHOD 8260

CLIENT: Griffin International PROJECT NAME: Tallman's Store

REPORT DATE: May 7, 1998

SAMPLER: L.T.R.

DATE SAMPLED: April 29, 1998

DATE RECEIVED: May 1, 1998

PROJECT CODE: GITS1452

ANALYSIS DATE: May 6, 1998 STATION: RS #5

REF.#: 119,914

TIME SAMPLED: 11:15

<u>Parameter</u>	Detection Limit (μg/kg)	Concentration As Received (µg/kg)
Benzene	5	45.9
Chlorobenzene	5	ND¹
1,2-Dichlorobenzene	5	ND
1,3-Dichlorobenzene	5	ND
1,4-Dichlorobenzene	5	ND
Ethylbenzene	5	26.1
Toluene	5	<b>70.</b> 7
<del>-</del>	10	68.4
Xylene MTBE	10	$TBQ^2$

### NUMBER OF UNIDENTIFIED PEAKS FOUND: >10

#### ANALYTICAL SURROGATE RECOVERY:

Dibromofluoromethane: 92.%
Toluene-d8: 94.%
4-Bromofluorobenzene: 100.%

PERCENT SOLIDS: 70.%

#### NOTES:

- 1 None detected
- 2 Trace below quantitation limit



32 James Brown Drive Williston, Vermont 05495 (802) 879-4333 FAX 879-7103

#### **REPORT OF LABORATORY ANALYSIS**

CLIENT: Griffin International

PROJECT NAME: Tallman's Store DATE REPORTED: May 7, 1998 DATE SAMPLED: April 29, 1998 PROJECT CODE: GITS1453

REF. #: 119,915

Enclosed please find the results of the analyses performed for the samples referenced on the attached chain of custody record.

Chain of custody did not indicate sample preservation.

All samples were prepared and analyzed by requirements outlined in the referenced methods and within the specified holding times.

All instrumentation was calibrated with the appropriate frequency and verified by the requirements outlined in the referenced methods.

Blank contamination was not observed at levels affecting the analytical results.

Analytical method precision and accuracy were monitored by laboratory control standards which included matrix spike, duplicate and quality control analyses. These standards were determined to be within established laboratory method acceptance limits.

Individual sample performance was monitored by the addition of surrogate analytes to each sample. All surrogate data was determined to be within Laboratory QA/QC guidelines unless otherwise noted.

Reviewed by,

Harry B. Locker, Ph.D. Laboratory Director

enclosures



32 James Brown Drive Williston, Vermont 05495 (802) 879-4333 FAX 879-7103

#### LABORATORY REPORT

## TOTAL PETROLEUM HYDROCARBONS (TPH) BY MODIFIED EPA METHOD 8015

DATE: May 7, 1998

CLIENT: Griffin International PROJECT: Tallman's Store PROJECT CODE: GITS1453 COLLECTED BY: L.T.R.

DATE SAMPLED: April 29, 1998 DATE RECEIVED: May 1, 1998

Reference #	Sample ID	Concentration As Received (mg/kg) <sup>1</sup>
119,915	RS #5; 11:15	151.

#### Notes:

1 Value quantitated based on the response of Gasoline Standards. Method detection limit is 1.0 mg/kg.

(802) 879-4333

32 James Brown Drive

Williston, Vermont 05495

#### CHAIN-OF-CUSTODY RECORD

26063

Project Name: TAII MAN'S Store Reporting Address: Billing Address: Site Location: Belvidere, ut Griffin GHSEIN Company: 6 rsen/ Contact Name/Phone #: Lourse Reed Endyne Project Number: Sampler Name: LTR GZTS 1453 -4288 Phone #: Sample Containers Lab# R A Sample Location Analysis Matrix Sample Date/l'ime Fleld Results/Remarks M Rush Required Preservation 4.29.98 No. Type/Size ANGLYZE SOI 250 8020 TP# 8015 1145 Relinquished by: Signature Received by: Signature soches Date/Time Relinquished by: Signature Received by: Signature Date/Time 10:00 New York State Project: Yes No Requested Analyses ρН TKN 11 Total Solids 16 Metals (Specify) 21 EPA 624 26 EPA 8270 B/N or Acid 2 Chloride Total P 12 TSS 17 Coliform (Specify) 22 EPA 625 B/N or A 27 EPA 8010/8020 3 Ammonia N Total Diss. P 8 13 TDS 18 COD 23 EPA 418.1 28 EPA 8080 Pest/PCB 4 Nitrite N 9 BOD, 14 Turbidity 19 BTEX 24 EPA 608 Pest/PCB 5 Nitrate N 10 Alkalinity 15 Conductivity 20 EPA 601/602 25 EPA 8240 29 TCLP (Specify: volatiles, semi-volatiles, metals, pesticides, herbicides) 30 Other (Specify):

32 James Brown Drive Williston, Vermont 05495 (802) 879-4333 CHAIN-OF-CUSTODY RECORD

26063

Project		: TAIII	MAN	15	Store			eporting	g Addre	ess:	· · · · · · · · · · · · · · · · · · ·			Billing	g Address:	60	,		
	ocation:				, ct			Grid	SCIN	<u> </u>	<u>.</u>	<u></u>				SPIN TO	/ 		
Endyn	e Proje	ct Number	r:	T.E	- 5 14 <u>5</u>	52	0	ompany ontact l	/: 6 i Name/F	hone #: L o	urre	Reed		Samp Phone	ler Name: L' #: 86	1 K	28	8	
Lab	*			le Local			Matrix	G R A	C O M P	Date/Time	Samp	ole Containers	F	ield Resi	ults/Remarks ANGLYZC	Analy Requi	red	Sample Preservation	Ru
19,9	) Luf	723	\\ \t	5			Soi/	حرّد ا		11:15		250 Anhr	Plea	use.	<b>拉</b>	80Z	2015	-	
11 11	<del>/)                                    </del>		<u> </u>		·.		<u> </u>	-				17/11.50	TO	500	R Lf	1			
								<del> </del>				<del> </del> -	Pa	<u>-pp</u>	10.18620	<b>()</b>			
								<del> </del>					10	5.3/.#	, ,,	<del></del>		<del></del>	<b></b>
						<u> </u>		<u> </u>			<del>-   -</del>		ļ						<del> </del>
													<u> </u>						├
							· · · · · · · · · · · · · · · · · · ·	<u> </u>					ļ		·				╄
										<u> </u>									
								+	<u> </u>	<u></u>	<del></del>		· · · · · · ·						
				<del></del>				+	<u> </u>	,			<del>- </del>		-				1
									<u> </u>	<u> </u>		<del>-</del>	<del>                                     </del>			<del>·</del>		<u></u>	+
				,	•••		<u></u>		<u> </u>					·		<u> </u>		<u> </u>	<u></u>
Relinqu	ished by	: Signature	1	er	M	/	1	Received	by: Signa	ature That	- 2	szel	<u>kus</u>	Date/I	Time 5	78	10	):00)	
Relinqu	iished by	r: Signature	Tu	uA	1	716C	la !	Received	by: Sign	na M.	Chan	Vices		Date/	Time 5-/-	98	/(	0:00	
ew Yor	rk State	Project: `	Yes	No	X					Requeste	ed Anal	yses							
1	Hq			11 6	Tital				Total Soli	ds	16	Metals (Specif	(y)	li	EPA CAT	26	E	PA 8270 B/N or	Acid
2	Chlori	de		7	Total P			12	TSS		17	Coliform (Spe	cify)	22	EPA 625 B/N or A	27	E:	PA 8010/8020	
3	Ammo	mia N		R	Testini	es. Γ		13	TDS		!8	COD		23	EPA 418,1	21	Е	PA 8080 Pest/PC	CB
4	Nitrite	N		9	BOD,			14	Turbidity		19	BTEX		24	EPA 608 Pest/PCB			··········	
5	Nitrate	»N		10	Alkalinit	ity		15	Conducti	vity	20	EPA 601/602		25	EPA 8240				
29	TCLP	(Specify; vola	tiles, sen	ni-volatile	es, metals, pe	esticides, h	erbicides)									·	<del>,</del>		
30	Other	(Specify):	_																

Williston, Vermont 05495

#### CHAIN-OF-CUSTODY RECORD

26063

Project Name: THI MAN'S Store Reporting Address: Billing Address: Site Location: Bolvidere, ct 61,8Pm Grissin Endyne Project Number: Sampler Name: LTK:
Phone #: US 4288 Company: 6 . S. C. Contact Name/Phone #: 1 con re liced Sample Containers Analysis Lab# Sample Location Matrix Sample Date/Time Field Results/Remarks Rush Required Preservation L1+79+48 No. Type/Size HUNKE 8020 TPH 8015 Ser 1 24 1 200 **36. 预验**证 かわな times and the second March S 10 7. **3** 400 Sec. 3. ..... 42 dir har 27 10.5 (0)± 1 2 (4) 產分 4. 1 1.466 . 1 - v. 1 \$60 GF (13-19)建设设备行动 V. 1 13.6 Mary Services Relinquished by: Signature Received by: Signature To HE 12 North Lo Date/Time Relinquished by: Signature Received by: Signature of Date/Time à ARKILL 40000 New York State Project: Yes No Requested Analyses TKN . 6 ° Total Solids 16 🖑 Metals (Specify) EPA 624 EPA 8270 B/N or Acid 2: Chloride Section. 7 3 Total P 12 TSS \*\*\* \*\*\* ASS 17.9 Coliform (Specify) 22 EPA 625 B/N or A EPA 8010/8020 3 Ammonia N 8 Total Diss. P 13 TDS 18 COD EPA 418.1 28 EPA 8080 Pest/PCB 4. Nitrite N BOD. 14 Turbidity 19 BTEX : EPA 608 Pest/PCB 5 Nitrate N . 10 Alkalinity 9343.5 Conductivity 20 EPA 601/602 EPA 8240 29 TCLP (Specify: volatiles, semi-volatiles, metals, pesticides, herbicides) 30 Other (Specify): 49 gr (570)